

## DAIGH COMPANY JOB STORIES #35. Rock Excavation NYC

Rock Removal: Da-mite used in conjunction with “hammer” to excavate large veins of pegmatite, some of which was 40ft wide . Unable to Break Rock with 10,000+ Hammer. Used IR 590 to drill 2 1/2” holes, 8ft-14ft deep.



Above: Red marks are the Drill Holes

Right: Cracks formed big enough to place hand between

Below: Cracks were large enough to allow Hammer to separate the rock and create “chunks” of rock



Excavation of “Whale’s Back” Complete

