

DAIGH COMPANY JOB STORIES #36. Rock Excavation inside home Summer 2007

Excavation inside house. Used Da-mite underneath home to help with excavation of rock.
Used Hand Drills to drill 1 3/4" holes on 18-inch centers. Depth 2ft to 5ft, dependent upon grade.



Above: Rock underneath home



Above: Drilling
1 3/4" holes



Right: Cracking



Above: Closer
view of cracking

Below: Partial



Above: Mini-excavator removing rock.



Left: Pile of Rock from excavation